




IES Photometric files RAU ARA  
Import the proper Iso-curves into your CAD drawing  
Iso curves in footcandles  
unit: feet




Mounting 9 feet



Mounting 10 feet



Mounting 11 feet



Mounting 12 feet

